Opus-Two

INSTRUMENT CONTROL SYSTEMS

Opus-Two Next Generation Generic CVE Hookup Diagram

+ −

| Power | Ethernet | uSD |

MIDI THRU

MIDI OUT

Option

Connector for 64IO cards

MIDI IN

Display Power/Data

| RS-485 | RFlex | Shoes | USB |

Expression Data Connections - Walker Shoes

→ To C-IV Analog Pin

→ Ground

→ 12 Volts

Expression Data Connections - Potentiometers

A1-A4 Sense Wires From Each Shoe

→ 5 Volts And Ground To All Pots

Note: When connecting a potentiometer, verify that the voltage connected to Analog Input Terminal (A1-A4) raises when the shoe opens, and lowers when the shoe closes.

→ Ground

→ To C-IV "Shoes" A1-A4 Analog Pin

→ To C-IV 5V Pin

−
D
+

Firmware Program

1 - Common
2 - No Connection
3 - Down
4 - Up
5 - Trans
6 - Track
7 - Play
8 - Record

1
2
3
4
5
6
7
8